Hyundai/Kia A4CF1, A4CF2

Sonnax®

1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA (800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

6

(1) 84741-07K

TCC Regulator Valve Kit

Helps cure:

- TCC apply/release problems
- Converter codes
- Loss of lube

(2) 84741-13K



Oversized Damper Clutch Control Valve Kit

Helps cure:

- Converter apply/release issues
- Excess slip RPM
- Cycling TCC RPM

Note: Requires tool kit F-84741-TL13 & the VB-FIX reaming fixture.

(3) 84741-01K

Boost Valve & Sleeve Kit

Helps cure:

- Insufficient line rise in drive ranges
- Higher-than-normal reverse pressures

• Soft shifts



Oversized Pressure Regulator Valve Kit

Helps cure:

- High/Low line pressure
- Soft and/or harsh shifts
- Clutch failure

Note: Requires tool kit 84741-TL3.

Upper Valve Body

Channel Plate

Lower Valve Body

> ©2014 Sonnax Industries, Inc. hax products listed here may be protected by one or more patents, or be patent pending

(1)

CUULID

(5)

4

6



Reducing Valve Kit

Helps cure:

- Low line pressure
- No TCC apply
- Delayed forward



Note: Requires tool kit F-84741-TL10 & the VB-FIX reaming fixture.



Oversized Pressure Control Valve Kit

Helps cure:

- Burnt clutches/brakes
- Shift complaints

Fits any of 3 locations



Note: Requires tool kit F-84741-TL16 & the VB-FIX reaming fixture.

Click on Sonnax part numbers to see more information.

